US Department of Transportation Federal Aviation Administration

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form A	\ppn	oved	
OMB	No.	2120	-002

For FAA Use Only

Office Identification

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. 1421). Failure to report can result in civil penalty not to exceed \$1,000 for each such violation (Section 901 Federal Aviation Act of 1958).

for ea	ch such	violation (Section 9	01 Federal Aviation A	ct of 195	i8).						
		Make Cessna		Model 140				,			
1. Aircr	aft	Serial No.			Nationality and Registration N		ark				
			on registration certific	cate)	Address (As shown on registration certificate)						
2. Owner Riverside Aircraft Sales Edward L. Moore Ouida Y. Moore			327 South Lewis Ave. Philadelphia, MS 39350								
			The data identified and is approved to inspection by a per Aviation Safety Inst	r the above	ve des orized	cribed aircraft si	rbject to a con 43.7.	conformity 2 - 2010			
					4. L	Init Identificati	on			5. Type	
U	Init		Make			Model		Serial No		Repair	Alteration
AIRFRA	ME			(As des	scribe	d in Item 1 abou	re)				
POWEF	RPLANT	Continental		0-20	0A			251835-A-48			х
PROPE	LLER										
APPLIA	ANCE	Type Manufacturer							•		
				(6. Co	nformity States	ment			***************************************	
A. Ager	ncy's Nar	me and Address			B. F	(ind of Agency			C. Certif	icate No.	
Edwa	ard L. N	4oore			_x_	U.S. Certificate	d Mechanic		A&P12	99567	
4175 Gann Store Road		Foreign Certificated Mechanic									
Hixson, TN 37343			Certificated Repair Station]					
		***************************************			<u></u>	Manufacturer			<u> </u>		
h	ave been	made in accordan	r alteration made to the nce with the requirement correct to the best of r	nts of Pa	art 43	of the U.S. Fed	above and eral Aviatio	described on the rev in Regulations and th	erse or att at the infor	tachments here mation	eto
Date					Sign	nature of Author	ized Individ	dual 🗪		V	***************************************
May	26, 20	10			1	dura	ud	1 m	me	-	
				7. Ap	prova	al for Return To	Service				
Pursu Admir	ant to the	e authority given po of the Federal Avia	ersons specified below tion Administration an	v, the uni d is	it iden	tified in item 4 v	vas inspec	ted in the manner pre REJECTED	scribed by	the the	
BY	FAA I Inspe	Fit. Standards ctor	Manufacturer		Insp	ection Authoriz	ation	Other (Specify)			
		Designee	Repair Station		Pen	son Approved b ada Airworthine	y Transpor ess Group	t			
Date of	Approva	or Rejection	Certificate or Designation No.		Sigr	nature of Author	ized Individ	dual			

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished
(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N1728V

Serial #13913

May 26, 2010

 This Form 337 seeks field approval of the use of engine crankcase mount arm boss adapters to preclude the requirement to change the aircraft engine mount in an STC approved engine replacement/ upgrade to this aircraft.

2. The original Continental (TCM) 85 HP, C85-12F, engine in this aircraft

- is being replaced with a TCM, 100 HP, 0-200A engine as approved under STC SA547EA. This engine change will result in minimum weight change and, in fact, it will probably result in an engine gross weight decrease since a modern lightweight starter and an alternator are on the 0-200A rather than the heavier Delco-Remy starter and generator used on the C85. TCM data indicates that there is less than two pound weight difference in the two basic engines. The C85-12 engine mounting arm end bosses have front and rear conical recesses for the TCM 22387 conical rubber bushings. (see attachment 1 photo 1 &2). The arm bosses of the 0-200A crankcase are bored through and counterbored for Lord J-3608-1 mount bushing assemblies. (see attachment 1 photo 3 & 4). Due to the increase in length of the Lord bushing over the TCM bushing, (see attachment 1 and compare photo 1 with photo 4), STC SA547EA requires the original engine mount to be replaced with a Cessna 0451111 mount (see attachment 2) which is approximately 1" shorter (firewall to engine) to compensate for the increase length of the Lord bushing assemblies.
- 3. It is proposed to use four pair of owner produced engine case mount arm boss, machined aluminum, adapters as inserts to reconfigure the 0-200A engine arm bosses to accept the original TCM 22387 conical bushings. (see attachment 1 photo 5). The TCM 22387 bushings are, in fact, approved for and used on other specified 0-200A engines. (see attachment 3). A TCM technical representative ("Ron" @ 1-888-826-5465) researched the 0-200A database and confirmed that certain aircraft manufacturers specified the 0-200 engines with mounting arm boss configurations that used the TCM 22387 conical bushings.
- 4. In this engine change, use of the TCM 22387 bushing should result in less engine movement in the aircraft enclosed cowling as opposed to the Lord bushing. TCDS E-233, C75 through C85 series engines

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

N 1728V

SERIAL # 13913

MAY 26, 2010

- 8. Description of Work Accomplished
 (If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)
 provides a caution statement in Note 4, line 4, regarding engine
 movement while using the Lord flexible mounts: "C75-15 and C85-15
 series engines are identical to the C75-12 and C85-12 series except
 they incorporate modified mounting lugs for for the Lord flexible
 mount assemblies. Increased engine motion results and must be
 provided for in the installation." (see attachment 4). This aircraft
 cowling was originally designed for use of the TCM 22387 bushings
 and continued use of this bushing should result in less engine engine
 movement with less cowling wear/stress.
 - 5. Each of the identical eight adapters is machined from 5056 aluminum stock. As seen in attachment 1 photo 6, each adapter outside shell has an end flange, a shoulder step, and a straight shank. When inserted into the engine mounting arm end boss, the flange end seats against the outer end of the boss, the shoulder step rests against the boss inner counterbore recess step where the Lord bushing inner washer would normally rest. The adapter outer shank is machined to fit inside the 0-200A arm boss. (see attachment 5 photo 1). The inner bore of the adapter is machined to accept the TCM 22387 conical bushing with a close fit. (see attachment 5 photo 2 and 3). When installed, the compression load, due to engine mount bolt torque, on the TCM 22387 bushing causes it to swell to a tight fit inside the adapter. (see attachment 5 photo 4 for a loose-fit mock-up of the proposed configuration on an 0-200A engine arm).
 - 6. When installing the 0-200A engine using the Lord mounts, the engine mount bolt nuts are torqued to 180-190 inch-pounds. With the TCM 22387 bushing/adapters installed, the torque will be reduced to 60-80 inch-pounds as specified in the TCM Overhaul Manual, X-30010, tightening torque table.
 - 7. Therefore, use ot he above owner produced adapters in conjunction with the TCM 22387 conical rubber mounts will result in reduced overall engine length and, thus, permit the continued use of the original engine mount.

8.	Upon completion of the engine change, the aircraft will be weighed
	and a new weight and balance schedule prepared.

-----END-----

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished
(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N1728V

SERIAL # 13913 MAY 26, 2010

INSTRUCTIONS FOR CONTINUED AIRWORTHINESS

Since this field approved alteration only addresses the use of owner produced engine mount arm boss adapters to preclude a required mount change per STC SA547EA, the instructions for continued airworthiness are limited to the original engine mount, the engine crankcase mount arm boss adapters, TCM 22387 rubber bushings, and engine mount bolt nut torque requirements.

- The engine mount is not changed as required by STC SA 537EA but the original mount is retained. Any repair/maintenance to said mount should follow porcedures outlined in applicable Cessna service manuals or AC43.13-1B.
- 2. The owner produced adapters become a permanent configuration change to the engine mount arm bosses in this aircraft. The only maintenance for these adapters is the usual condition inspections during required periodic inspections.
- 3. The rubber mount bushings are stock TCM 22387 parts and can be readily obtained and replaced "on-condition" as required during periodic inspections.
- 4. Per paragraph 6 of this Form 337 field approval, use ot the adapters and TCM 22387 bushings require a reduced torque of 60-80 inchpounds on the engine mount bolt nuts as specified in the TCM Overhaul Manual, X30010, tightening torque table.
- 5. Any changes or revisions to this document will be submitted to the appropriate FAA FSDO for approval.


-----END----




1



2




3



1



5



PROPOSED OWNER PRODUCEDADAPTER

6

ATTACHMENT 1

Thompson's Air 4375 Six B Road Anderson, California 96007 July 8, 2005

INSTALLATION INSTRUCTIONS (STC SA547EA)

Install a Continental O-200A engine in a Cessna 120,140 or 140A as follows:

- 1. Install a Cessna Engine Mount, part number 0451111, on the firewall using NAS 145 or AN-5 hardware as specified in the Illustrated Parts Catalog.
- Install a Continental O-200A Engine on this mount using Lord Mounts. (Dynaflex Engine Mount Kit # 52-3-137 or equalivant)
- 3. Install the same engine baffling as used on the original engine.
- Install a Blast Tube (Cessna Part Number 0450240 or equalivant) as on the C90-14F Engine and Baffle Installation.
- 5. Install a Cowling Doubler. (Part Number 0452208 or equalivant) as per Cessna Installation Instructions for that doubler.
- 6. Remark the engine instruments to the following limits:

Oil Temp

225 degree F. Red Line

Cylinder Head Temp

525 degree F. Red Line

Oil Pressure

(When this instrument is used) 30-60 PSI, Red Line @60PSI

Maximum RPM

2750 RPM Red Line @

- 7. Install a mixture control cable (Cessna Part Number 0411090-22 or equalivant), cut to necessary length, clamping it to the engine mount in two places, aft of the oil sump and to the right side of the exhaust stack brace with Adel clamps.
- 8. Install the same engine exhaust mufflers as used on the Continental C-90-14F.
- 9. Connect the carburetor heat hose to the heater muff. Do not connect this heat muff to a pressure scoop assembly #0450266 (Heater Air Intake), as this assembly will lower the carburetor air heat rise below the minimum.
- 10. Install one of the following propellers:
 - A. McCauley 1A100 set to dimensions 6950-54 21lbs (-50)
 - B. McCauley 1A101 set to dimensions 6948-54 211bs (-50)
 - C. Sensenich 69CK set to dimensions 6948-52 24lbs (-50) (Re-calculate weight and balance adding 3 lbs at -50 inch moment)

May 26,2010 Serial #13913 N1728V 020 G75 COCO FIG. 12345 DESCRIPTION PART NUMBER INDEX \$ @ Gasket 530928 3-7 Flange - 8 530163 ATTACHING PARTS Washer, Plain 1/4 Inch 12 - 9 20522 Washer, Lock 1/4 Inch 12 12 12 12 12 -10 MS35337-44 Nut, 1/4 Inch 12 12 12 12 12 -11 646605 \$ Connector 8 8 8 8 8 539840 -12 Clamp 16 16 16 16 16 -13 536388-1.25 \$ Gasket, Oil -14 22344 O Cover -15 35033 ATTACHING PARTS 3 3 -16 2473 ... Lock 5/16 Inch 3 3 MS35337-45 -17 J., Plain 5/16 Inch 3 3 2439 -18 1 Pivot, Starter Pinion -19 23487 -19A 643231 @@ Adapter Assembly, Starter Clutch 1 1 ② Bearing, Needle -19B 633609-8 ① Dowel 28 \$ Bushing 8 21 FIGURE 3. CRANKCASE'ASSOCIATED PARTS 19A 14 20

DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION



E-233 Revision 17 CONTINENTAL C75-8, -8F, -8FH, -8FHJ, -8FJ, -8J C75-12, -12F, -12FH, -12FHJ, -12FJ, -12J C75-12B, -12BF, -12BFH C75-15, -15F C85-8, -8F, -8FHJ, -8FJ, -8J C85-12, -12F, -12FH, -12FHJ, -12FJ, -12J C85-14F C85-15, -15F August 15, 1973

TYPE CERTIFICATE DATA SHEET NO. E-233

Engines of models described herein conforming with this data sheet (which is part of type certificate No. 233) and other approved data on file with the Federal Aviation Administration, meet the minimum standards for use in certificated aircraft in accordance with pertinent aircraft data sheets and applicable portions of the Federal Aviation Regulations provided they are installed, operated and maintained as prescribed by the approved manufacturer's manuals and other approved instructions.

Type Certificate Holder

Teledyne Continental Motors Mobile, Alabama 36601

Model Type	C75-8 4H0A	C75-12, -15	C85-8	C85-12, -14, -15
Rating, ICAO or ARDC standard atmosphere				
Max. continuous hp., r.p.m., full throttle at sea level pressure altitude	75-2275		85-2575	
Takeoff hp., 5 min., r.p.m. full throttle at	75-2275		85-2575	

NOTE 4.

The C75-8 series engines are similar to the C75-12 and C85-12 series except that they do not incorporate provisions for generator and starter drives.

The C85 series engines are similar to the corresponding C75 series except for rating and a different carburetor

The C75-12B engine is similar to the C75-12 except that it incorporates a Stromberg PS-3 pressure carburetor (P/N 224) at weight increase of 3 lb. See NOTE 3 for first one

The C75-15 and C85-15 series engines are identical to the C75-12 and C85-12 series except that they incorporate modified mounting lugs for Lord flexible mount assemblies. Increased engine motion results and must be provided for in the installation.

Co. 141 is the same as the Co. 121 except that it incorporates provisions for modified mounting lugs for Lord flexible mounting assemblies that are used on the C90-I4F engine.

Those models listed in the heading of this data sheet suffixed by letters F, H and J, differ from the basic model designation as follows:

"F" denotes an SAE No. 1 flanged crankshaft rather than 0 taper, at weight increase of 1 lb.

"H" denotes a special SAE No. 1 flanged crankshaft and special crankcase for installation of hydraulically operated controllable pitch propeller requiring oil supply through crankshaft.

"J" denotes a fuel injector. Ex-Cell-O model A-41 (P/N 40572) or Ex-Cell-O model B-41 (P/N Ex-A40791) instead of a carburetor, at weight increase of 4 lb.

Page No.	1	2	3	
Rev. No.	17	17	17	


Reformatted 1/95




PROPOSED ADAPTER WITH TCM 22387 CONICAL BUSHING

2

1





4

3