65
US Department
of Transportation
Federal Aviation
Administration

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

	For FAA Use Only
Form Approved OMB No. 2120-0020 2/28/2011	Electronic Tracking Number

INSTRUCTIONS: Print or type all entries. See Title 14 CFR §43.9, Part 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. §44701). Failure to report can result in a civil penalty for each such violation. (49 U.S.C. §46301(a))

	lation. (49 U.S.		o roport to requir	Ju	2, ian	(.5 0.0	3 . 47	~ . ,			suit in a civil penalty for each	
Nationality and Registration Mark							Serial No.					
4 Ain	N93655	N93655					978					
1. Aircraft	Make	Make								Series		
	Engine	Engineering & Research Company (ERCO)					Ercou	ре			419-C	
	Name (As	Name (As shown on registration certificate)					Address (As shown on registration certificate)					
2. Owner									S. Sherm	an Dr.		
z. Owner							1		napolis -		State Indiana	
	Earl H E	Brosman		_				4623		Coun	try USA	
3. For FAA Use Only The data identified herein complies with the applicable airworthiness requirements and is approved for the above described aircraft, subject to conformity inspection by a person authorized in FAR 43, Section 43.7 5/18/2012												
4.	Туре			5.	Unit le	dentifica	ation					
Repair	Alteration	Unit	Ма	ke		-			Model		Serial No.	
		AIDEDALIE				_	(As described in Item 1 above)			1 ahove)		
		AIRFRAME				_	(A3 U		ed iii iteiii			
		POWERPLANT	Г									
		PROPELLER										
		APPLIANCE	Type Manufacturer									
		1	6	. C	onforn	nity Sta	tement			del marche constante de la constante		
A. Agency	's Name and A	ddress	Francisco de la Paris de Maria de La Caractería de Caractería de Caractería de Caractería de Caractería de Car	В	. Kind	of Agend	су					
	on C Wright			1	✓ U. S. Certificated Mechanic Manufa						nufacturer	
	20 W 850 N						ficated Me			icate No.		
400	orntown	LICA	State Indiana	L			icated Repair Station					
Zip 460	071-9611 co	untry USA		L	Cer	tificated I	Maintenanc	e Orgai	nization	Ap3159	903966IA	
D. I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.												
Extended range fuel per 14 CFR Part 43 App. B Signature/Date of Authorized Individual												
			7 40	nro	Nat fo	r Potur						
7. Approval for Return to Service Pursuant to the authority given persons specified below, the unit identified in item 5 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is Approved Rejected												
BY	FAA Flt. Stand	dards Man	ufacturer				ganizatio	n	Persons Approved by Canadian Department of Transport			
	FAA Designee	nee Repair Station Ir			Other (Specify)							
	n No. 103966IA		ature/Date of Authoriz		- 1	dual C	8/30	1/2	צוט			
FAA FOI	rm 337 (10-06)		. /	- 1	//							

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N93655 5-9-2012

Nationality and Registration Mark

Date


Installed shoulder harness attachment brackets and reinforcement angles fabricated from .050" 2024 T-3 aluminum to aft fuselage tail cone at frame "F". This installation duplicates two previous Field Approval FAA Form 337. First; dated July 17, 1996, on an Ercoupe 415C, N94196 S/N 1519, with the exception of using any FAA approved harness insted of the Hooker brand harness. Second; dated March 4, 2005, on an Ercoupe 415C N3794H S/N 4419 with the exception of using any FAA approved harness instead of the Aircraft Spruce harness. Any FAA approved shoulder harness/seat belt may be used.

The installation drawings are attached, labeled "Shoulder Harness Installation In Ercoupe N93655".

Work was accomplished IAW AC 46.13-1b, Chapter 4, Sections 3 & 4, and AC 43.13-2a, chapter 9, sections 1,2,&3. Aircraft was weighed and weight and balance updated in aircraft this date.

INSTRUCTIONS FOR CONTINUED AIRWORTHINESS

- 1. Introduction: The original Erco model 415 design did not provide for occupant shoulder harness. This installation alteration enhances safety aspects for pilot and passenger by providing a shoulder restraint system when used in conjunction with existing seat belts.
- 2. Description: The restraint system is installed IAW the attached drawing: "Shoulder Harness Installation in Erocoupe N93655". This installation does not affect with any component or system in the aircraft.
- 3. Control, operation information: N/A
- 4. Service information: N/A
- 5. Maintenance instructions: Inspection intervals are concurrent with the aircraft inspection procedures.
- 6. Trouble shooting information: N/A
- 7. Removal and replacement information: Standard maintenance practices apply.
- 8. Diagrams: Installation drawing is attached.
- 9. Special inspection requirements: N/A
- 10. Application of special treatments: N/A
- 11. Data: Standard aircraft hardware and general torque specifications apply.
- 12.List of special tools: N/A
- 13. For commuter category aircraft: N/A
- 14. Recommended overhaul periods: N/A
- 15. Airworthiness limitations section: N/A
- 16.Revisions: Revision of these instructions shall be accomplished by submitting a letter to the local FSDO office with a copy of the revised FAA form 337 and revised instructions.



SHOULDER HARNESS INSTALLATION ERCOUPE 4ISC N93655